



Dear Valued Customer,

You are receiving this email as part of a notification to a Dometic/Sierra recall notice.

You have purchased an item that could be affected.

Please see the below information on how to identify if the product you have is affected and how to obtain a replacement.

Please email us at [support@wholesalemarine.com](mailto:support@wholesalemarine.com) with any questions.

Thank You

[Wholesale Marine](#)

**\*\*No items are to be returned to Wholesale Marine, please contact Dometic directly to setup a replacement under the recall if your unit is found to be affected.**

Sierra has identified a concern on select gasoline fuel water separators that utilize a water collection bowl, which may contain a faulty collection bowl thread ring. These fuel water separators were manufactured from 11/21/2021 through 4/30/2022, The faulty bowl thread ring may not allow the water collection bowl to be properly torqued to the fuel canister, which can cause a fuel leak.

The defect may affect the following Sierra part numbers:

# RECALL NOTICE

SIERRA ANNOUNCES RECALL OF FUEL WATER SEPARATORS



<u>SIERRA PART NUMBER</u>	<u>DESCRIPTION</u>
18-78866	Fuel Water Separator
18-78867	Fuel/Water Separating Filter with Clear Collection Bowl
18-79913	FWS Gas Kit 1/4" Aluminum Head & Clear Bowl
18-79914	FWS Gas Kit 3/8" Aluminum Head & Clear Bowl
18-79915	FWS Gas Kit 1/4" Aluminum Head
18-79916	FWS Gas Kit 3/8" Aluminum Head
18-7919	Fuel Water Separator Filter
18-7929	Fuel Water Separator Assembly
18-7938	Fuel Water Separator Kit
18-7951	Fuel Water Separator Kit

18-7928-1	Racor Style Fuel Water Separator
18-7932-1	Racor Style Fuel Water Separator
18-7937-1	Racor Style Fuel Water Separator
18-7920	Fuel Water Separator Filter
18-7943	Fuel Water Separator Assembly
18-7941-1	Racor Style Fuel Water Separator
18-7948	Fuel Filter 10 Micron
18-7969	Fuel Water Separator Kit
18-7994-1	FWS Assy Racor O/B W/O Brkt S3227
18-99189	FWS Gas Kit 320R 10 Micron
18-99289	FWS Gas Kit 320UL 10 Micron
18-7949	Fuel Filter 10 Micron

### **IMPORTANT**

**Hazard:** Fuel Water Separator may leak between the canister and collection bowl.

**Recalled product:** See attached list.

**Action Required:** Consumers should contact Sierra Tech Support to return product.

For more information:

877-663-8396

[techservices@dometic.com](mailto:techservices@dometic.com)

Monday – Friday 7:30am – 4:30pm CT

This recall is being conducted in cooperation with the U.S Coast Guard: Case # Pending

PLEASE POST IN PROMINENT LOCATION

## How to find the date code:

This is a potential safety issue, and we recommend that any customer who purchased a fuel filter or fuel filter kit described in this bulletin to suspend use and return it to Sierra International. We sincerely regret the necessity for this action, but we are certain that you will agree that safety comes first. Thank you in advance for your understanding and support.

**FIGURE A**

